



**OPD OESCHGER** Art. 53.119.40-67

# Montageanleitung Mounting Instruction Instructions de montage Istruzioni di Montaggio
















, "Н"	1		"L"			ı "X"								
	555	600	640	685	725	224	256	288	320	352	384	416	448	480
600 - 632	Х					Х	Х	Х						
633 - 664	Х					Х	Х	Х	Х					
53.119.40-43 53.119.50-53 53.119.60-63		Х				Х	Х	Х	Х	Х				
53.119.44-47 53.119.54-57 53.119.64-67			Х			Х	Х	Х	Х	Х	Х			
729 - 760				Х		Х	Х	Х	Х	Х	Х	Х		
761 - 792				Х		Х	Х	Х	Х	Х	Х	Х	Х	
793 - 824					Х	Х	Х	Х	Х	Х	Х	Х	Х	Х









"H"	1		"L"			ı "X"								
	555	600	640	685	725	224	256	288	320	352	384	416	448	480
600 - 632	Х					Х	Х	Х						
633 - 664	Х					Х	Х	Х	Х					
53.119.40-43 53.119.50-53 53.119.60-63		Х				Х	Х	Х	Х	Х				
53.119.44-47 53.119.54-57 53.119.64-67			Х			Х	X	Х	X	Х	X			
729 - 760				Х		Х	Х	Х	Х	Х	Х	Х		
761 - 792				Х		Х	Х	Х	Х	Х	Х	Х	Х	
793 - 824					Х	Х	Х	Х	Х	Х	Х	Х	Х	Х


**1**x

\_\_\_\_ 2x




**2**x

























Seite 10





Seite 11


**2**x





2

# Art. 53.119.40-67



Demontage Dismounting Demontage Sementaggio

